

# BS6696T | TAPED HI VIS COOL LIGHTWEIGHT SHIRT



Vertical cotton mesh back ventilation

Underarm cotton mesh ventilation

Two piece contrast coloured structured collar

Pen division on left chest pocket

Two chest pockets with button down flaps

Reflective taped hoop pattern

Single turned centre front opening

Two button adjustable sleeve cuff

Shaped curved hem



HI VIS  
1906.4:2023



DAY & NIGHT USE  
4602.1:2024



NIGHT TIME USE ONLY  
4602.1:2024  
TT20 ONLY



SUN PROTECTION  
50+



INDUSTRIAL



STATIC CONTROL



fresche



COOL LIGHTWEIGHT



## FEATURES

- / Reflective taped hoop pattern
- / Two chest pockets with button down flaps and pen division
- / Two piece contrast coloured structured collar
- / Vertical cotton mesh back ventilation
- / Underarm cotton mesh ventilation
- / Left pocket with pen division
- / Two button adjustable sleeve cuff
- / Platinum Partner of NBCF embroidery (TT33 & TT34 colourways only)
- / Blue/Navy (TT20) night compliant only
- / Bisley exclusive Fresche® antimicrobial treatment to prevent against bacteria, mould and viruses

## COLOURS

Yellow/Navy (TT01)  
Orange/Navy (TT02)  
Yellow/Khaki (TT16)  
Yellow/Charcoal (TT23)  
Lime/Charcoal (TT36)  
Yellow/Royal (TT43)  
Orange/Royal (TT44)  
Yellow/Pink (TT33)  
Orange/Pink (TT34)  
Blue/Navy (TT20)

## SIZES

S - 6XL  
XS - 6XL (TT01,TT02,TT20 & TT44 only)  
Traditional Fit

## FABRIC

100% Cotton Preshrunk Drill,155gsm  
100% Cotton Open Mesh,125gsm

## AUSTRALIAN AND INTERNATIONAL STANDARDS

- / AS/NZS 2621:1998 Textiles - Guide to the Selection of Correct Care Labelling Instructions from AS/NZS 1957
- / AS/NZS 2392:1999 Textiles - Labelling of Clothing, Household Textiles & Furnishing
- / AS/NZS 1957:1998 Textiles - Care Labelling
- / AS/NZS 2622:1996 Textiles Products - Fibre Content Labelling
- / AS 4399:2020 Sun Protection Clothing - Evaluation and Classification
- / AS/NZS 1906.4:2023 Hi Visibility Materials For Safety Garments
- / AS 4602.1:2024 Hi Visibility Safety Garments. Garments for High Risk Application
- / AS/NZS 1020:1995 The Control of Undesirable Static Electricity
- / ASTM D5489-07 Standard Guide for Care Labelling Code Using Symbols for Care Instructions on Textile Products
- / ISO 14184-1 Textiles - Determination of Formaldehyde - Part 1: Free and Hydrolized Formaldehyde (Water Extraction Method)

